

Product Safety Recall

Mechpro Model: MP2540 2.5 HP Air Compressor direct drive 40 litre air tank



Sold by Repco stores between December 2009 and August 2011.

Defect: A manufacturing defect may give rise to a short circuit in the motor potentially causing it to overheat.

Hazard: Due to overheating of various components in the compressor motor, a plastic connector may catch on fire.

What to do: Customers should immediately stop using the product and return the compressor to your nearest Repco store for a refund or replacement.

For more information please call 1800 268 876 or

Austech Industries Pty Ltd
PO Box 715, Archerfield
Qld Australia 4108
(07) 3723 1500
www.austechindustries.com.au

Exego limited
362 Wellington Rd
Mulgrave Victoria 3170
(03) 9566 5444
www.repco.com.au

**See www.recalls.gov.au for
Australian Product Recall Information**